

NEWS

STRUCTURES

Load bearing wall removal suspected in building collapse



Collapse: what is left of the building

By John McKenna

Engineers this week said that the collapse of a four-storey retail property in Hertfordshire appeared to have been caused by the removal of part of a load bearing wall.

Early on Sunday morning the front of the period property on Berkhamsted High Street suffered a catastrophic failure.